



# **DTO28 lifts saved!**

**Drop-In Rack and Pinion Equalizer Upgrade Kit**



**STOP**

Rotary DTO28 equalizer box cave-ins from causing premature and costly lift replacement.

SVI's **Drop-In Rack and Pinion Equalizer Upgrade Kit** is the solution DTO28 lift owners have been seeking.



The new kit includes: racks bars, housings, pinions, guide tubes, locking system and all the hardware.

This kit provides DTO28 lift owners with a real service solution. Many DTO28 lifts have one problem in common, the equalizer box corrodes and begins caving-in.

This condition causes the crossbeam portion of the existing equalizer mechanism to hang up and impair or completely stop the lifts function. While, there is nothing else wrong with the lift, lift owners in the past were faced with two costly options, replace the lift or

excavate and install a new equalizer—**this is over!**


The SVI **Rack and Pinion Upgrade Kit** increases the usable service life of DTO28 lifts. Many DTO28 lifts are in service facilities deemed national accounts by the lift manufacturer. Why sacrifice service facility dollars through unnecessary lift replacement? DTO lift owners would rather save their DTO keeping its versatility and avoiding the expense of a new lift. SVI is your answer!

Installation of the SVI Drop-In Rack and Pinion Equalization system is simple. For all the specific details contact SVI for more details.

DTO28 lifts were produced by Rotary lift and can be readily found in the following locations: Muffler Shops, Tire Dealerships and Car Dealerships.



This DTO28 was raised nightly for floor cleaning. One day it just simply would not go back down.



Sealed guide tube system shown lowered in place.



Save the DTOs

Lift Repair: SVI is your answer!



**SVI International, Inc.**  
**LIFT REPAIR PARTS**

**BALTIMORE - CHICAGO - LOS ANGELES**

Main Office: 155 Harvestore Dr. • DeKalb, Illinois 60115 • 800-321-8173 • Fax 800-899-1784

All names, numbers, symbols and descriptions are used for reference purposes only. Entire contents copyright © SVI International, Inc. 2018