


# cassette/pit lift **Aqua-out**

an  patent pending product

One nice shop. . .



**Prevent potential out of sight, out of mind problems. When was the last time you actually looked below the surface?**

The cassette style lifts in this shop were only recently installed. Every time these lifts are raised fresh, moist air is drawn in to the containment tub. Down below the cool surroundings cause moisture in the air to condense. This condensed moisture (water) accumulates and starts its almost termite like assault on the lift. Up until now there has been no simple solution to automatic water removal. **SVI is your answer!**

There really is something you can actually do to reduce the water level automatically. **Install Aqua-out. . .**

Trouble free? Or,

is something lurking below.

**At SVI we don't simply tell you there is water down there; SVI actually does something about it.**



- Water
- Rust
- Corrosion

## **Aqua-out**

**For use on cassette and pit style in-ground lifts.**

Remove the center cover and take a look for yourself. What do you see?



# **Get the water out now!**


- Aqua out**
- Protects your investment.
  - Removes water.
  - Works automatically.
  - Air operated.
  - Eliminates routine periodic pump out maintenance.
  - An SVI lift industry solution.

## **Aqua-out**

The Aqua-out automatic water removal system installs in about two hours and gets the water out of your lift every time the lift is lowered or the air valve is actuated. Aqua-out incorporates a moisture filter/regulator, pump and an in-line filter that are all specially designed for the rigors of service your application demands.

Prolong the life of your investment and don't put this installation off another day. Contact your local SVI distributor to schedule an installation. This low cost solution is worth every penny because you spent a lot of dollars to buy these lifts, now protect the investment.

### **the Aqua-out system**



**SVI is your answer!**

**This corroded air lock cylinder was recently removed from a lift. Could other parts be corroding as well?**

## **SVI International, Inc. AUTO LIFT SOLUTIONS**

**BALTIMORE - CHICAGO - LOS ANGELES**

Main Office: 101 W. Illinois Ave • Aurora, Illinois 60506  
800-321-8173 • Fax 800-899-1784



Entire Contents Copyright © SVI International, Inc. 2005